Promise™
EPOXY

Follow Us!
@PromiseEpoxy
PromiseEpoxy.com
(888) 792-3579

TECHNICAL DATA SHEET
DEEP POUR EPOXY

Deep Pour Epoxy is a high performance two component clear epoxy system designed for river tables, encapsulations, DIY projects, and home decor requiring a deeper pour beyond a simple surface coat. The material has an easy to use 2 to 1 volume mix ratio and has excellent air release qualities while having a long work time for those larger pours.

PRODUCT FEATURES

- Self-Leveling, High Gloss
- Excellent Air Release
- Excellent Color Stability
- Produces a Tough, High Gloss, Water Resistant Finish
- Blush Resistant
- Crystal Clear Depth

PRODUCT SPECIFICATIONS

Mix Ratio by Volume	2 Part Resin : 1 Part Hardener
Work Time (100 gram mass)	50-70 minutes
Demold Time	3 days
Full Cure Time	7 days
Ultimate Shore Hardness	D65
Temperature Resistance	110F
Shelf Life	1 year unopened 6 months opened.
Color	Clear

BEFORE USE: Thoroughly read Safety Data Sheets, product labels and the "SAFETY" section in this Technical Data Sheet.

IMPORTANT: PLEASE NOTE

- It is critical that your frame or mold is watertight. Frames should be built out of material that can easily dissipate heat.
- We do not recommend pouring over bark, as bark can hold excessive air and moisture.
- This product should not be poured directly over an oil-based paint or stain, as oil and epoxy do NOT mix. There should be a definitive barrier between the two products. We suggest applying a water-based clear coat over the oil-based product. If the water-based clear coat leaves a high gloss or shine, we suggest scuffing the surface with 320-grit to allow the epoxy to properly adhere. Once sanded, clean the surface thoroughly with Isopropyl Alcohol. Then you can apply the epoxy.
- This product is not intended for permanent outdoor use or direct UV exposure. It does contain UV inhibitors to help resist yellowing, but all epoxy products will eventually begin to yellow. This includes the base resin, curing agent, as well as the finished cured products.
- This product may be used to embed or encapsulate items for viewing and display.
- When mixing the Curing Agent and Base Resin, any cloudiness should clear up. If the product appears cloudy or is not crystal clear after mixing, contact our customer support team before applying to your final project.
- This product can be mixed with pigment powders and liquid dyes to achieve your desired color. Do not mix any oil or water-based products with the resin. When in doubt, test a sample batch to ensure you can achieve your desired color without issues.

BEFORE YOU BEGIN

WORK ENVIRONMENT: The ideal working temperature is around 65-75°F in a clean, dry, dust-free environment. Avoid working in high humidity. If you are pouring in large volumes of 2 or more gallons, we suggest keeping room temperature closer to 65°F. We highly recommend keeping fans on your project to help dissipate heat.

COVERAGE: You can use the coverage calculator on our website to determine the volume of mixed resin that you will need before you begin your project. Please remember, this is not an exact science, as each project is different and each substrate will absorb the epoxy differently. As the product fills the cracks and crevices in your mold, the level may drop. Be prepared to add more epoxy as needed. The calculator does not take into account embedded objects. It is always best to have more than enough material on hand to ensure completion of your project.

MIXING & POURING

When measuring epoxy for use, stick with the recommended ratios in the instructions (for best results), and blend just what you think you'll need - as once mixed – leftover epoxy can't be saved. You're better off making several small batches as you progress with your project; aside from saving on material - epoxy has a limited working time until the the curing process begins. Depending upon the ambient conditions (temperature & humidity) – you'll have about 90 minutes. For best results – the adage is to cure epoxy resin warm (room temperature is fine), slow and long (allow sufficient drying time).

STEP 1: Prepare 2 parts Base Resin (Part A) and 1 part Curing Agent (Part B) by liquid volume. Pour the Curing Agent first and then the Base Resin into a clean, smooth-sided container large enough to hold all of the liquid, allowing room for mixing without spillage. Use graduated mixing containers help to ensure properly measured amounts of Part A and B. Any variance in this mix ratio may result in curing issues.

STEP 2: The material must be mixed thoroughly for at least 5-10 minutes. Be sure to scrape the sides, corners and bottom of container as you mix. Be careful not to whip excessive air into the mixture. If mixing a gallon, use a power mixer set to "hand speed". For smaller quantities, use stir sticks. Do not mix more than 3 gallons at one time. If you need to mix several batches, be sure to use a clean, dry container for each batch. Using the same container may lead to curing issues.

Revsion Date 07/10/2025

Promise™ EPOXY

TECHNICAL DATA SHEET
DEEP POUR EPOXY
CONTINUED

STEP 3: Pour the mixed resin into the mold or onto the surface of the project. Do NOT scrape out the last of the resin onto your project as unmixed epoxy on the sides or bottom of the container could contaminate your project, leading to curing issues.

STEP 4: To remove air bubbles that have risen to the surface of the poured resin, use a heat gun or torch in a sweeping motion across the surface, holding the heat source approximately 6-1O inches away from the surface until no bubbles remain. Avoid heating any one spot for too long so as to prevent any distortions in the finish.

STEP 5: Curing times can vary greatly by project, depending on mass and temperature. Full cure and maximum hardness can require up to 3-5 days. Do not use or place any items on your project during this time.

CLEAN UP & DISPOSAL

Tools can be cleaned with Isopropyl Alcohol or a residue-free cleaner. Do not use soap and water.

Dispose of product and container according to federal, state and local regulations. Store any remaining product in the original bottles, tightly sealed and locked up in a cool, dry environment.

SAFETY

SAFETY: Before use, thoroughly read Safety Data Sheets and product labels. Follow safety precautions and directions.

- Wear gloves to protect skin
- Safety glasses
- Protect clothing with a work smock or other outer garment
- For cleaning surfaces, containers – use Acetone, rubbing alcohol or nail polish remover
- When stored separately, epoxy & hardener have long shelf lives – store in a cool dry area in tightly sealed containers

RESIN: Keep out of reach of children. Avoid breathing vapors. Use with adequate general or local exhaust ventilation to minimize exposure levels. If needed, a NIOSH-approved respirator with organic vapor cartridge may be used. If inhaled, remove victim to fresh air and keep at rest in a position comfortable for breathing. Wear impervious gloves, such as butyl rubber or nitrile rubber. Wash skin thoroughly with soap and water after handling. Take off contaminated clothing and wash it before reuse. If skin irritation occurs, get medical help. Wear eye protection, such as chemical safety glasses/googles. If in eyes, rinse cautiously with water for several minutes, removing contact lenses if present and easy to do. If eye irritation persists, get medical help.

HARDENER: Keep out of reach of children. Do not eat, drink, or smoke when using this product. If swallowed, rinse mouth and get medical help. Use with adequate general or local exhaust ventilation to minimize exposure levels. If needed, a NIOSH-approved respirator with organic vapor cartridge may be used. If inhaled, remove victim to fresh air and keep at rest in a position comfortable for breathing. Wear impervious gloves, such as butyl rubber or nitrile rubber. Wash skin thoroughly with soap and water after handling. Wear eye protection, such as chemical safety glasses/googles. If in eyes, immediately rinse with water for several minutes, removing contact lenses if present and easy to do. If eye irritation persists, get medical help.

WARNING: THE EPOXY CURE REACTION IS VERY EXOTHERMIC. Do not apply in thicknesses greater than the recommended maximum application thickness for the product. DOING SO CAN CAUSE WARPING AND EVEN A FIRE.

DISCLAIMER: The information contained herein is considered accurate; however, Promise Epoxy makes no warranty regarding its accuracy. The user must determine the suitability of the product for the intended use and accepts all risk and liability associated with that use.

Revsion Date 07/10/2025